

03500.015513.



PATENT APPLICATION

CofC
4

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:

Shuji YAMADA et al.

Appln. No.: 09/847,420

Filed: May 3, 2001

For: ELECTRON SOURCE FORMING
SUBSTRATE, AND ELECTRON
SOURCE AND IMAGE DISPLAY
USING THE SAME

)
: Examiner: Anthony T. Perry
)
: Group Art Unit: 2879
)
: U.S. Patent No.: 6,815,884 B2
)
: Issued: November 9, 2004
)
: July 18, 2005
)
:

Certificate

JUL 21 2005

of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

ATTENTION: CERTIFICATE OF CORRECTIONS BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

07/19/2005 SSITHIB1 00000024 6815884

01 FC:1811


100.00 0P

Required Fee

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Please charge any additional fees or credit any overpayment to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Attorney for Patentees
Gary M. Jacobs
Registration No. 28,861

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
GMJ:ayr

DC_MAIN 198950v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S) : YAMADA, et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS IN FIGURE 11:

"AMPLE" should read --AMPULE--.

ON THE COVER PAGE AT (57) ABSTRACT

Line 8, "makes" should read --making--.

Line 9, delete ", even".

Line 10, delete "elapsing longer time".

COLUMN 1:

Line 27, "Molybdenium" should read --Molybdenum--.

Line 31, "Recio" should read --Radio--.

COLUMN 2:

Line 6, "reveled" should read --revealed--.

COLUMN 3:

Line 66, "an" should read --a--.

COLUMN 4:

Line 6, "an" should read --a--.

Line 37, "electro-emitting" should read --electron-emitting--.

COLUMN 5:

Line 18, "iron" should read --ion--.

Line 25, "iron" should read --ion--.

MAILING ADDRESS OF SENDER:
FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile
FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,815,884 B2
No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S) : YAMADA, et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 67, "view" should read --view- --.

COLUMN 7:

Line 44, "view point" should read --viewpoint--.

Line 45, "view point" should read --viewpoint--.

Line 48, "view point" should read --viewpoint--.

COLUMN 8:

Line 14, "e;lectron-emitting" should read --electron-emitting--.

Line 19, "AI," should read --Al,--.

Line 40, "view point" should read --viewpoint--.

COLUMN 10:

Line 19, "an" should read --and an--.

COLUMN 13:

Line 23, "a ample," should read --an ampule--.

Line 37, "an" should read --a--.

COLUMN 14:

Line 44, "Doy 1" should read --D_{oy1}--.

Line 45, "Doyn" should read --D_{oyn}--.

COLUMN 15:

Line 38, "resistor 104" should read --register 104--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,815,884 B2

No. of add'l. copies

@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S) : YAMADA, et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16:

Line 58, "Doy 1," should read --D_{oy1}--.

Line 59, "Doy n," should read --D_{oyn}--.

COLUMN 17:

Line 12, "D_{x₁₀})" should read --D_{x₁₀})--.

Line 65, "tow", should read --two--, and "the image forming" should read --image forming--.

COLUMN 18:

Line 29, "iron" should read --ion--.

COLUMN 19:

Line 63, "view" should read --view- --.

MAILING ADDRESS OF SENDER:
FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile
FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,815,884 B2
No. of add'l. copies
@ 30¢ per page

GMJ:ayr

DC_MAIN 198951v1

03500.015513.

PATENT APPLICATION

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
Shuji YAMADA et al.) : Examiner: Anthony T. Perry
Appln. No.: 09/847,420) : Group Art Unit: 2879
Filed: May 3, 2001) : U.S. Patent No.: 6,815,884 B2
For: ELECTRON SOURCE FORMING) : Issued: November 9, 2004
SUBSTRATE, AND ELECTRON) : July 18, 2005
SOURCE AND IMAGE DISPLAY) :
USING THE SAME) :

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

ATTENTION: CERTIFICATE OF CORRECTIONS BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Required Fee

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Please charge any additional fees or credit any overpayment to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Attorney for Patentees
Gary M. Jacobs
Registration No. 28,861

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
GMJ:ayr

DC_MAIN 198950v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S) : YAMADA, et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS IN FIGURE 11:
“AMPLE” should read --AMPULE--.

ON THE COVER PAGE AT (57) ABSTRACT

Line 8, “makes” should read --making--.

Line 9, delete “, even”.

Line 10, delete “elapsing longer time”.

COLUMN 1:

Line 27, “Molybdenum” should read --Molybdenum--.

Line 31, “Recio” should read --Radio--.

COLUMN 2:

Line 6, “reveled” should read --revealed--.

COLUMN 3:

Line 66, “an” should read --a--.

COLUMN 4:

Line 6, “an” should read --a--.

Line 37, “electro-emitting” should read --electron-emitting--.

COLUMN 5:

Line 18, “iron” should read --ion--.

Line 25, “iron” should read --ion--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,815,884 B2

No. of add'l. copies

@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S) : YAMADA, et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 67, "view" should read --view- --.

COLUMN 7:

Line 44, "view point" should read --viewpoint--.

Line 45, "view point" should read --viewpoint--.

Line 48, "view point" should read --viewpoint--.

COLUMN 8:

Line 14, "e;lectron-emitting" should read --electron-emitting--.

Line 19, "Al," should read --Al,--.

Line 40, "view point" should read --viewpoint--.

COLUMN 10:

Line 19, "an" should read --and an--.

COLUMN 13:

Line 23, "a ample," should read --an ampule--.

Line 37, "an" should read --a--.

COLUMN 14:

Line 44, "Doy 1" should read --D_{oyl}--.

Line 45, "Doyn" should read --D_{oyn}--.

COLUMN 15:

Line 38, "resistor 104" should read --register 104--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,815,884 B2

No. of add'l. copies

@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,815,884 B2

DATED : November 9, 2004

INVENTOR(S) : YAMADA, et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16:

Line 58, "Doy 1," should read --D_{oy1}--.

Line 59, "Doy n," should read --D_{ogn}--.

COLUMN 17:

Line 12, "Dx_{x10})" should read --D_{x10})--.

Line 65, "tow", should read --two--, and "the image forming" should read --image forming--.

COLUMN 18:

Line 29, "iron" should read --ion--.

COLUMN 19:

Line 63, "view" should read --view- --.

MAILING ADDRESS OF SENDER:
FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile
FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,815,884 B2
No. of add'l. copies
@ 30¢ per page

